

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Power Flume No. 1
(Tacoma Project)
Tacoma Vicinity
La Plata County
Colorado

Martin G. Robbins, Photographer 1980

CO-17-1 through CO-17-10: original photographs in files of Colorado-Ute Electric Association, Inc. Montrose, Colorado.

- CO-17-1 Photocopy of photograph--1905 (2 1/4 X 2 1/4" negative)
VIEW DURING CONSTRUCTION
- CO-17-2 Photocopy of photograph--1910 (2 1/4 X 2 1/4" negative)
GENERAL VIEW SHOWING TIMBER BRACES
- CO-17-3 Photocopy of photograph--May 5, 1917 (2 1/4 X 2 1/4" negative)
GENERAL VIEW SHOWING EFFECTS OF LEAKAGE
- CO-17-4 Photocopy of photograph--August 24, 1927 (2 1/4 X 2 1/4" negative)
RECONSTRUCTION
- CO-17-5 Photocopy of photograph--1927 (2 1/4 X 2 1/4" negative)
GENERAL VIEW OF RECONSTRUCTION SHOWING CRADLE
- CO-17-6 Photocopy of photograph--September 28, 1927 (2 1/4 X 2 1/4" negative)
GENERAL VIEW
- CO-17-7 Photocopy of photograph--ca. 1927 (2 1/4 X 2 1/4" negative)
DETAIL SHOWING ADAPTATION THAT ALLOWED USE OF UPPER END OF
ORIGINAL FLUME AND LOWER END JUST RECONSTRUCTED
- CO-17-8 Photocopy of photograph--1928 (2 1/4 X 2 1/4" negative)
VIEW OF RECONSTRUCTED FLUME SHOWING TIMBER BENTS
- CO-17-9 Photocopy of photograph--September 1928 (2 1/4 X 2 1/4" negative)
VIEW OF RECONSTRUCTED FLUME SHOWING TIMBER BENTS
(note treatment of long span)
- CO-17-10 Photocopy of photograph--1928 (2 1/4 X 2 1/4" negative)
INTAKE TO FLUME AND VENTURI

CO-17-11 SIDE VIEW--1980

CO-17-12 GENERAL VIEW SHOWING TYPICAL SECTION OF FLUME--1980

CO-17-13 TOP VIEW OF TYPICAL SECTION OF FLUME--1980

CO-17-14 SIOE VIEW OF TYPICAL SECTION OF FLUME SUPPORTEO BY
TRESTLE--1980

CO-17-15 FRONTAL VIEW OF FLUME AND TYPICAL TRESTLE--1980

CO-17-16 SIDE VIEW SHOWING DETAIL OF TYPICAL SECTION OF
FLUME--1980

CO-17-17 SIOE VIEW; OETAIL TOP OF FLUME--1980

CO-17-18 FRONTAL VIEW; FLUME INTAKE--1980

CO-17-19 TOP VIEW; FLUME EMPTYING INTO FOREBAY LAKE--1980

CO-17-20 SIOE VIEW; FLUME EMPTYING INTO FOREBAY LAKE--1980